

TOYOTA LAND CRUISER PRADO
Stock ID 381209

Registration Year: 2022
Manufacture Year: 2022

Vehicle Specifications

| | | | | | | | |
|-----------------------|---------|------------------------|-------------------|--------------------|----------------------|------------------|-------------|
| Model: | | Chassis No: | JTEBR3FJ90K249364 | Grade: | KAKADU (FULL OPTION) | Fuel: | Diesel |
| Engine: | 1GD-FTV | Drive Train: | 4WD | Dimensions: | 19 M ³ | Shape: | SUV |
| Engine No: | 2023 | Transmission: | AT | Mileage: | 60200 | Capacity: | 2800cc |
| Ext. Color: | | Weight (kg): | | Seats: | 7 | Color: | |
| Certification: | | Classification: | | Exterior: | BROWN | Interior: | BLACK BEIGE |

Vehicle images



Vehicle Options

| | | | | | | | | | |
|----------------|-----|-------------------|-----|-----------------|-----|------------------------|-----|---------------|-----|
| Pwr Steering | Yes | Pwr Wind | Yes | Pwr Mirrors | Yes | Center Lock | Yes | Air Cond | Yes |
| Reverse Camera | Yes | Pwr Slide Door | | Easy Closer | | Cruise Control | | ABS | |
| Air Bag | Yes | Fog Lamps | Yes | HID Head Lamps | | LED Head Lamps | | Spare Key | |
| Remote Key | | Push Start | Yes | Seat Heater | | Pwr Seat | Yes | Leather Seat | Yes |
| Floor Mat | | Sun Roof | Yes | Alloy Wheels | Yes | Grill Guard | | Rear Wiper | |
| Rear Spoiler | Yes | Stereo (FULL) | | Navi/TV | | CD Player | | Car MD | |
| AUX | | Spare Tire | Yes | Spare Tire Case | | Puncture Repairing Kit | | Tool | |
| Jack | | Operators Manual | | Maint. Record | | 360 Degree Camera | Yes | AM/FM Radio | Yes |
| 4WD | Yes | 2WD | | Back Tire | | TV | Yes | Body Kit | Yes |
| Side Skirts | Yes | Front Lip Spoiler | Yes | Turbo | | Side Airbag | Yes | Wheel Spanner | |
| ESC | | Keyless Entry | | | | | | | |

