

LEXUS RX Stock ID 330572 Registration Year: 2011 Manufacture Year: 2011

Vehicle Specifications

| Model: | | Chassis No: | AGL10-2415513 | Grade: | RX270 | Fuel: | Petrol |
|----------------|--------|-----------------|---------------|--------------------|-------------------|-----------|--------|
| Engine: | 1AR-FE | Drive Train: | 2WD | Dimensions: | 16 M ³ | Shape: | SUV |
| Engine No: | 2023 | Transmission: | AT | Mileage: | 149700 | Capacity: | 2700сс |
| Ext. Color: | 212 | Weight (kg): | | Seats: | 5 | Color: | |
| Certification: | | Classification: | | Exterior: | BLACK | Interior: | BLACK |

Vehicle images



Vehicle Options

| Pwr Steering | Yes | Pwr Wind | Yes | Pwr Mirrors | Yes | Center Lock | Air Cond | Yes |
|----------------|-----|-------------------|-----|-----------------|-----|------------------------|---------------|-----|
| Reverse Camera | Yes | Pwr Slide Door | | Easy Closer | | Cruise Control | ABS | |
| Air Bag | Yes | Fog Lamps | Yes | HID Head Lamps | | LED Head Lamps | Spare Key | |
| Remote Key | | Push Start | Yes | Seat Heater | | Pwr Seat | Leather Seat | Yes |
| Floor Mat | | Sun Roof | Yes | Alloy Wheels | Yes | Grill Guard | Rear Wiper | |
| Rear Spoiler | | Stereo (FULL) | | Navi/TV | | CD Player | Car MD | |
| AUX | | Spare Tire | | Spare Tire Case | | Puncture Repairing Kit | Tool | |
| Jack | | Operators Manual | | Maint. Record | | 360 Degree Camera | AM/FM Radio | Yes |
| 4WD | | 2WD | Yes | Back Tire | | TV | Body Kit | |
| Side Skirts | | Front Lip Spoiler | | Turbo | | Side Airbag | Wheel Spanner | |
| ESC | | Keyless Entry | | 4 | | | | |