

TOYOTA HILUX
Stock ID 204412

Registration Year: 1996
Manufacture Year: 0

Vehicle Specifications

| | | | | | | | |
|-----------------------|------|------------------------|---------------|--------------------|-------------------|------------------|---------|
| Model: | | Chassis No: | LN108-5001028 | Grade: | | Fuel: | Diesel |
| Engine: | 2L | Drive Train: | 4WD | Dimensions: | 15 M ³ | Shape: | PICK UP |
| Engine No: | 2023 | Transmission: | AT | Mileage: | 251900 | Capacity: | 2400cc |
| Ext. Color: | | Weight (kg): | | Seats: | 5 | Color: | |
| Certification: | | Classification: | | Exterior: | BLACK SILVER | Interior: | GRAY |

Vehicle images



Vehicle Options

| | | | | | | | | | |
|----------------|------------|-------------------|------------|-----------------|------------|------------------------|------------|---------------|--|
| Pwr Steering | <i>Yes</i> | Pwr Wind | <i>Yes</i> | Pwr Mirrors | <i>Yes</i> | Center Lock | <i>Yes</i> | Air Cond | |
| Reverse Camera | | Pwr Slide Door | | Easy Closer | | Cruise Control | | ABS | |
| Air Bag | | Fog Lamps | | HID Head Lamps | | LED Head Lamps | | Spare Key | |
| Remote Key | | Push Start | | Seat Heater | | Pwr Seat | | Leather Seat | |
| Floor Mat | | Sun Roof | | Alloy Wheels | <i>Yes</i> | Grill Guard | | Rear Wiper | |
| Rear Spoiler | | Stereo (FULL) | | Navi/TV | | CD Player | | Car MD | |
| AUX | | Spare Tire | | Spare Tire Case | | Puncture Repairing Kit | | Tool | |
| Jack | | Operators Manual | | Maint. Record | | 360 Degree Camera | | AM/FM Radio | |
| 4WD | <i>Yes</i> | 2WD | | Back Tire | | TV | | Body Kit | |
| Side Skirts | | Front Lip Spoiler | | Turbo | | Side Airbag | | Wheel Spanner | |
| ESC | | Keyless Entry | | | | | | | |

